PRODUCTION PROCESS

12 Steps | Permanent Magnetic Chuck Manufacturing



01

Aluminum Component Cutting



02

Punching & Drilling




03

Pole Plate Assembly



06

Base Machining & Drilling




05

Steel Plate Machining



04

Steel Plate Flame Cutting



07

Magnet Bonding



08

Chuck Assembly




09

Side & Surface Milling




12

Product Packaging



11

Quality Inspection



10

Surface Coating